



FIG. 1



F I G . 2



F I G . 3




FIG. 4







FIG. 5




F I G. 6 A



F I G. 6 B



F I G . 7 A



F I G . 7 B



FIG. 8 A

FIG. 8 B

FIG. 8 C




FIG. 9A

FIG. 9B

FIG. 9C





FIG. 10A

j \ i	0	1	2	3
0	0	3	6	9
1	4	7	10	13
2	8	11	14	17
3	12	15	18	21
4	16	19	22	25
5	20	23	26	29
6	24	27	30	33

FIG. 10B



Step \ Pass	1	2	3	4
t=0	①			
1				
2				
3	②			
4		①		
5				
6	③			
7		②		
8			①	
9	④			
10		③		
11			②	
12				①
13		④		
14			③	

FIG. 11A




FIG. 11B




FIG. 11C




FIG. 12 A




FIG. 12 B




FIG. 13A




FIG. 13B




FIG. 14 A




FIG. 14 B




FIG. 15




FIG. 16 A




FIG. 16 B




FIG. 17 A




FIG. 17 B




FIG. 17 C




FIG. 17 D

